


This technical drawing shows a side view of a double-row fastener assembly. It consists of two vertical strips, each with a series of rectangular fasteners. The left strip is labeled with callouts 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, and 11. The right strip is labeled with callouts 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, and 11. The fasteners are arranged in two rows, with the top row being slightly offset from the bottom row. The drawing is a black and white line drawing with hatching used to indicate different materials or cross-sections.

Fig. 1 is a side view of a vertical strip 46. The strip features a series of square openings 9 along its length. On the right edge of the strip, there are pointed protrusions 7. The strip is labeled 46 at the bottom left, and the openings are labeled 9 at the top right and middle right. The protrusions are labeled 7 at the top right.

Fig. 4






Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13





Fig. 14






Fig. 15

Fig. 16





Fig. 17